

PRIME TIME PARTY RENTAL 5225 N SPRINGBORO PIKE WEST CARROLLTON, OHIO 45439

(937) 296-9262

www.PrimeTimePartyRental.com

If you are experiencing difficulties, please refer to our instruction videos before calling the emergency line.

ULTRA 60 SPECIAL SERIES POPCORN MACHINE





- 1. Turn all 3 swithces "ON".
- 2. For first batch only, let kettle hear for approximately 4 minutes.
- 3. Add premeasure 6 oz. popcorn and oil pouch in kettle.
- 4. When popcorn starts to overflow, dump the kettle to prevent popcorn from burning.
- 5. Repeat steps 3 and 4 immediately, always making 3 to 5 batches for best popcorn results.
- 6. When popping final batch, turn the kettle heat switch off when popcorn begins lifting the lid.

NOTES:

Keep kettle motor and heat switches "OFF" when not popping.


Keep doors open when popping.

Keep doors closed when your are finished popping corn.

Do not immerse the kettle, warmer or any part of this equipment in water.

To avoid serious burns, do NOT touch the kettle while it is hot.

SAFETY PRECAUTIONS





A CAUTION

Do NOT allow direct contact of this equipment by the public when used in food service locations. Only personnel trained and experienced in the equipment operation may operate this equipment.

Carefully read all instructions before operation.



A CAUTION

This machine is NOT to be operated by minors.

007GENC041